

Table of Contents

FOREWORD	iii
1. SCOPE AND PURPOSE	1
1.1 SCOPE.....	1
1.2 PURPOSE.....	1
2. BACKGROUND.....	2
3. OBSERVED EFFECTS	3
4. THEORY OF TRIBOCHARGING	5
4.1 SURFACE CONTACT EFFECTS"	5
4.2 THE INFLUENCE OF MATERIAL WORK FUNCTION'	6
4.3 CHARGE LIMITERS - CHARGE BACKFLOW ⁴	6
4.4 CHARGE LIMITERS - GASEOUS BREAKDOWN ⁴	7
4.5 SUMMARY OF TRIBOCHARGING THEORY	7
5. CONSIDERATIONS FOR TRIBOCHARGE MEASUREMENT	8
5.1 GUIDELINES TO CONSIDER WHEN DEVELOPING A TEST	8
5.2 VARIABLES THAT EFFECT TRIBOELECTRIC CHARGING TESTING.	9
6. APPENDICES - TEST METHODS FOR EVALUATING TRIBOELECTRIC CHARGING	10
7. APPENDIX A: MAGAZINES.....	16
7.1 SCOPE AND PURPOSE	16
<i>7.1.1 Scope.....</i>	16
<i>7.1.2 Purpose.....</i>	16
7.2 REFERENCED PUBLICATIONS	16
7.3 REQUIRED EQUIPMENT	16
7.4 TEST PROCEDURE	17
7.5 REPORTING	18
7.6 CALCULATE MEAN AND STANDARD DEVIATION - SAMPLE TEST DATA	18
8. APPENDIX B: INCLINE PLANE METHOD - LARGE CYLINDERS.....	23
8.1 SCOPE AND PURPOSE	23
<i>8.1.1 Scope.....</i>	23
<i>8.1.2 Purpose.....</i>	23
8.2 REFERENCED PUBLICATIONS	23
8.3 REQUIRED EQUIPMENT	24
8.4 TEST PROCEDURE	24
8.5 REPORTING	25
8.6 SAMPLE TEST DATA	25
9. APPENDIX C: INCLINE PLANE METHOD - SMALL CYLINDERS.....	30
9.1 SCOPE AND PURPOSE	30
<i>9.1.1 Scope.....</i>	30
<i>9.1.2 Purpose.....</i>	30
9.2 REFERENCED PUBLICATIONS	30
9.3 REQUIRED EQUIPMENT	31
9.4 TEST PROCEDURE	31
9.5 REPORTING.....	32

9.6 SAMPLE TEST DATA	32
10. APPENDIX D: CHARGING DUE TO TRANSPORT OR HANDLING IN PACKAGING MATERIALS	36
10.1 PURPOSE AND SCOPE	36
<i>10.1.1 Scope</i>	36
<i>10.1.2 Purpose</i>	36
10.2 REFERENCED PUBLICATIONS	36
10.3 REQUIRED EQUIPMENT	37
10.4 TEST PROCEDURE	37
10.5 REPORTING	38
10.6 SAMPLE TEST DATA	38
11. APPENDIX E: CARD PULL TEST	40
11.1 SCOPE AND PURPOSE	40
<i>11.1.1 Scope</i>	40
<i>11.1.2 Purpose</i>	40
11.2 REFERENCED PUBLICATIONS	40
11.3 REQUIRED EQUIPMENT	40
11.4 TEST PROCEDURE	41
11.5 REPORTING	41
11.6 SAMPLE TEST DATA	41
12. APPENDIX F: HAND HELD CHARGING TEST	43
12.1 PURPOSE AND SCOPE	43
<i>12.1.1 Scope</i>	43
<i>12.1.2 Purpose</i>	43
12.2 REFERENCED PUBLICATIONS	43
12.3 REQUIRED EQUIPMENT	44
12.4 TEST PROCEDURE	44
12.5 REPORTING	45
12.6 SAMPLE TEST DATA	45
13. APPENDIX G: ROLLING FRICTION TESTER	47
13.1 SCOPE AND PURPOSE	47
<i>13.1.1 Scope</i>	47
<i>13.1.2 Purpose</i>	47
13.2 REFERENCED PUBLICATION	47
13.3 REQUIRED EQUIPMENT	48
13.4 TEST PROCEDURE	48
13.5 REPORTING	50
13.6 SAMPLE TEST DATA	50
14. APPENDIX H. ADHESIVE TAPE PULL TEST	54
14.1 SCOPE AND PURPOSE	54
<i>14.1.1 Scope</i>	54
<i>14.1.2 Purpose</i>	54
14.2 REFERENCE PUBLICATIONS	54
14.3 REQUIRED EQUIPMENT	55
14.4 SAMPLE PREPARATION, CONDITIONING AND TEST CONDITIONS.....	55
<i>14.4.1 Unwind Test</i>	55
<i>14.4.2 Removal from a Surface</i>	56
14.5 REPORTING	56
14.6 SAMPLE TEST DATA	56
15. REFERENCES	60

Table of Figures

<i>Figure 1 Tribocharging of Insulators and Conductors</i>	12
<i>Figure 2 Tribocharging of a person on a carpet</i>	13
<i>Figure 3 Surface of Tribocharging Materials</i>	13
<i>Figure 4 Structures of Matter</i>	14
<i>Figure 5 Illustration of Charge Exchange</i>	15
<i>Figure 6 Sliding Device</i>	19
<i>Figure 7 Equipment Setup for Inclined Plane - Small Cylinders</i>	33
<i>Figure 8 Hand Held Charging Test Fixture</i>	46
<i>Figure 9 Sketch of rolling friction tester showing its basic components</i>	51
<i>Figure 10 Drawing of cylinder with metal shaft inserted</i>	51
<i>Figure 11 Tape Unwind Test</i>	57
<i>Figure 12 Tape Removal From a Surface</i>	58