

TABLE OF CONTENTS

1.0 INTRODUCTION.....	1
2.0 ESD ISSUES IN THE FPD MANUFACTURING ENVIRONMENT.....	1
2.1 DIRECT CONTACT PROCESS FIXTURE AND STAGE MATERIAL ANALYSIS.....	1
2.1.1 <i>Introduction</i>	1
2.1.2 <i>ESD Safe Material Analysis</i>	2
2.1.3 <i>Static Charge Generation by Stage Materials</i>	6
2.1.4 <i>Section Summary</i>	11
2.2 GLASS PLATE TRANSFER SYSTEM	11
2.2.1 <i>Introduction</i>	11
2.2.2 <i>ESD Damage in Transfer System</i>	12
2.2.3 <i>Section Summary</i>	16
2.3 GENERAL SOURCES OF ESD DAMAGE IN FPD PRODUCTION	16
3.0 FACTORY CONTROLS FOR FPD	16
3.1 STATIC CHARGE CONTROL.....	16
3.1.1 <i>Limitations of General ESD Control</i>	16
3.1.2 <i>Other Material Properties</i>	16
3.2 CHARGE GENERATION	17
3.2.1 <i>Triboelectric Charging</i>	17
3.2.2 <i>Limits on Humidity Control of Charge Generation</i>	17
3.3 GROUNDING CONDUCTORS AND STATIC DISSIPATIVE MATERIALS.....	17
3.4 PERSONNEL STATIC CHARGE CONTROL.....	18
3.5 NEUTRALIZING CHARGE ON INSULATORS.....	18
3.6 IONIZATION	18
3.7 PROBLEMS WITH CONTROLLING STATIC CHARGE IN MANUFACTURING EQUIPMENT	19
3.8 STANDARDS.....	19
4.0 OUTLOOK.....	19
4.1 DISPLAY TECHNOLOGY FUTURE DEVELOPMENT TRENDS	20
4.2 QUANTUM DOTS	20
4.3 CURVED AND FLEXIBLE DISPLAYS.....	21
4.4 4K UHD AND HIGH RESOLUTION PPI DISPLAYS	21
4.5 LTPS AND IGZO	21
4.6 OLEDs	22
4.7 LCDs.....	22
4.8 TRANSPARENT DISPLAYS	22
4.9 GLASS SLIMMING	22

Annexes

Annex A (Informative): Glass Plate Generation Sizes.....	24
Annex B (Informative): Abbreviations	25
Annex C (Informative): Bibliography.....	26
Annex D (Informative): Reference Documents.....	27

Tables

Table 1: Lift Pin Resistance Measured Values Related to ESD Damage	3
Table 2: Lift Pin Resistance Measured Values for Different Materials	4
Table 3: Tested Stage Resistance Range.....	7
Table 4: Stage Material Properties	10
Table 5: Characteristics of Two Rollers in Transfer Units	15

Figures

Figure 1: Failures Correlate with the Lift Pin Locations on Process Stage for 8th Generation Glass Substrate.....	2
Figure 2: TFT LCD ESD Damage Features	3
Figure 3: Schematic of Test (a) Glass and (b) Lift Pin	4
Figure 4: Test Setup for ESD Damage Occurrence During Lift Pin Contact.....	4
Figure 5: ESD Damage Occurrence versus Different (a) Resistance Ranges of Lift Pins, (b) Air Gap Spacing, and (c) Breakdown Damage Image of a 3 µm Gap	6
Figure 6: Stage Equipment for the Glass Separation Test.....	6
Figure 7: Charge Generation Test Results for Different Stage Material Resistance for (a) Bare Glass and (b) Passivation Layer on Glass	8
Figure 8: Static Charge Voltages Increasing with the Number of Separations	8
Figure 9: Static Charge Generation Values on a Granite Stage with Different Surface Roughness	9
Figure 10: Static Charge Generation Values with Different Process Conditions (a) Separation Speed, (b) Vacuum Holding Pressures, and (c) Vacuum Time	11
Figure 11: Loupe Image of Point Defect.....	12
Figure 12: The Defect Map in Glass	12
Figure 13: Physical Failure Analysis of Defect	14
Figure 14: Schematic Diagram of Panel Structure	14
Figure 15: Transfer Unit Where the ESD Occurred.....	15